

### **SUMMARY** 1234 Main Street Muskogee OK 74403 #70002691, InterNACHI CPI #21062167, 03/15/2024 9:00AM

Ray Roberts Oklahoma Licensed Home Inspector International Association of Certified Indoor Air Consultants # IAC2-93995



This Summary Report includes the items that were, in my opinion, the most important items to bring to your attention. This is not by any means a substitute for the full report. Please read the entire report.





2.2.1 Roof Drainage Systems

### DOWNSPOUTS DRAIN NEAR HOUSE

**BACK PORCH** 



One or more downspouts drain too close to the home's foundation. This can result in excessive moisture in the soil at the foundation, which can lead to foundation/structural movement. Recommend a qualified contractor adjust downspout extensions to drain at least 6 feet from the foundation.

Here is a helpful DIY link and video on draining water flow away from your house.

Recommendation Recommended DIY Project



# 3.2.1 Siding, Flashing & Trim **EVIDENCE OF WATER INTRUSION**




Siding showed signs of water intrusion. This could lead to further siding deterioration and/or mold. Recommend a qualified siding contractor evaluate and repair.

Recommendation Contact a qualified professional.









### 3.3.1 Exterior Doors

### DOOR DOES NOT CLOSE OR LATCH



Door does not close or latch properly. Recommend qualified handyman adjust strike plate and/or lock.

Here is a DIY troubleshooting article on fixing door issues.

Recommendation Contact a qualified door repair/installation contractor.



#### 3.3.2 Exterior Doors

### **DOOR SILL/TRIM**



Door sill and/or trim is loose, deteriorated or worn and repair or replacement should be considered.

Recommendation

Contact a qualified door repair/installation contractor.



### 3.4.1 Walkways, Patios & Driveways

### **DRIVEWAY CRACKING - MINOR**



Minor cosmetic cracks observed, which may indicate movement in the soil. Recommend monitor and/or have concrete contractor patch/seal.

Recommended DIY Project







# 5.2.1 Refrigerator ICE MAKER NOT WORKING KITCHEN



Ice maker was not working on the date of inspection.

Recommendation Contact a qualified professional.



### 5.3.1 Range/Oven/Cooktop BURNER BARELY HEATING

KITCHEN

Burner on stove barely heating up.

Recommendation Contact a qualified professional.





### 5.4.1 Garbage Disposal

### **EXCESSIVE NOISE**

Garbage disposal was excessively noisy.

Here is a helpful DIY troubleshooting video.

Recommendation Contact a qualified professional.





### 6.3.1 Windows **DAMAGED**



One or more windows appears to have general damage, but are operational. Recommend a window professional clean, lubricate & adjust as necessary. Fix/ remove cracked plactic on side of windows.

Recommendation Contact a qualified window repair/installation contractor.



6.3.2 Windows **MISSING SCREEN** 



Window missing screen. Recommend replacement.

Recommendation

MASTER BATHROOM

Recommended DIY Project



6.5.1 Walls

MINOR HOLE IN WALL

Recommendation

Contact a qualified professional.







### 9.3.1 GFCI & AFCI NO GFCI PROTECTION INSTALLED



HALL BATHROOM

No GFCI protection present in all locations. Recommend licensed electrician upgrade by installing ground fault receptacles in all locations.

Here is a link to read about how GFCI receptacles keep you safe.

Recommendation

Contact a qualified electrical contractor.



### 10.4.1 GFCI & AFCI

### NO GFCI PROTECTION INSTALLED



MASTER BATH

No GFCI protection present in all locations. Recommend licensed electrician upgrade by installing ground fault receptacles in all locations.

Here is a link to read about how GFCI receptacles keep you safe.

Recommendation

Contact a qualified electrical contractor.



10.4.2 GFCI & AFCI

### **LOW FLOW**

MASTER BATHEOOM

Low flow when both showerheads are running. Recommend cleaning showrheads.

Recommendation

Recommended DIY Project








### 11.3.1 Floors

### **STAINED GROUT LINES**

**DINING ROOM** 



Recommendation Recommended DIY Project





### 11.6.1 Thermostat Controls

### **LOOSE THERMOSTAT**

HALLWAY

Thermostat was loose. Recommend repair or replacement.

Recommendation

Contact a qualified HVAC professional.





### 11.8.1 GFCI & AFCI **LOOSE OUTLET**

LIVING ROOM Recommendation Contact a qualified professional.






### 13.1.1 Cooling Equipment **UNIT NOT WORKING**



**EXTERIOR SOUTHEAST** 



Recommendation



## 14.5.1 Countertops & Cabinets **CABINET HINGE LOOSE**



KITCHEN

One or more cabinet hinges were loose. Recommend a qualified handyman or cabinet contractor repair.

Here is a helpful DIY article on cabinet repairs.

Recommendation Recommended DIY Project



16.1.1 Ceiling CRACKED DRYWALL

GARAGE CEILING Recommendation Recommended DIY Project





16.6.1 Occupant Door (From garage to inside of home)



### **NOT SELF-CLOSING**

GARAGE

Door from garage to home should have self-closing hinges to help prevent spread of a fire to living space. Recommend a qualified contractor install self-closing hinges.

### DIY Resource Link.

Recommendation

Contact a qualified door repair/installation contractor.

